

Project: Alaska Copper	Inst	Technician: David DuBois			
Project No.: 19ACW1					
System Performance:					
Was system running during the	inspection? Yes	⊠ No			
Flow Rates (gpm)	Influent 100	Effluent n/a	The flows should be ~155 gpm	ı	
Bag Filter #1 Pressures (psi)	Influent 8	Effluent 8	The bag filters should be replained if differential pressure > 8 psi	ced	
Bag Filter #2 Pressures (psi)	Influent 6	Effluent 5			
Carbon Filter Pressures (Lead)	Influentn/a	Effluent n/a	The carbon filters should be backflushed if differential		
Carbon Filter Pressures (Lag)	Influent <u>n/a</u>	Effluentn/a	pressure > 8 psi		
Were the bag filters replaced?	☐ Yes 🗵 No				
Was the carbon backflushed?	☐ Yes 区 No				

Maintenance and Inspection Checklist:

Task	Completed (Y/N)	Issues/Notes/Comments
Walchem Controller Inspected	⊠ Yes □ No	
Flow Meters Inspected	⊠ Yes □ No	
Level Sensor Cleaning/Inspection	⊠ Yes □ No	
Inspect System Plumbing	☑ Yes ☐ No	
Pumps Inspected	☑ Yes ☐ No	
General Housekeeping	☑ Yes ☐ No	
Chemistry Level	☑ Yes ☐ No	~70 gal
Safety Materials Inspected	☑ Yes ☐ No	
pH Probe Inspection/Calibration	☑ Yes □ No	



Water Sampling:								
Were water samples taken? ☐ Yes ☒ No								
Raw water:	pH <u>6.41</u>	Turbidity 5.14	NTU					
Bag Filter Influent	pH7.19	Turbidity 4.34	NTU					
Bag Filter Effluent	pH 7.11	Turbidity 3.04	NTU					
Carbon Filter Influent	pH <u>n/a</u>	Turbidity n/a	NTU					
Carbon Filter Effluent	pHn/a	Turbidityn/a	NTU					
Monthly Tasks:								
Were samples submitte	ed to Analytical?	☐ Yes ⊠ No						
Analytical Lab:								
Was Walchem data do	wnloaded?	☐ Yes ☒ No						
Were the tank sludge levels checked? ☐ Yes ☒ No								
Sludge Depth (inches):								
Decant Tank: n/	a							
Treatment tank:n/	a							
Backflush tank:n/	<u>a</u>							
Main lift station:n/	<u>a</u>							
North lift station:n/	a							
South lift station:n/	<u>a</u>							
Additional Comments, Recommendations and System Upsets:								
David DuBoi	S	Project Lead Te	ch	7/8/19				
Technician		Title		Date				

Submit

Page 2 of 2